9.4.3 Case Study, The Visitor Center at Zion National Park, Utah (Public Assembly/Retail/Office)

Building Design

Vistors Center (1) 8,800 SF Comfort Station (2) 2,756 SF Fee Station 170 SF

<u>Shell</u>

Windows

Type
South/East Glass
Double Pane Insulating Glass, Low-e, Aluminum Frames, Thermally Broken
Double Pane Insulating Glass, Heat Mirror, Aluminum Frames, Thermally Broken
Double Pane Insulating Glass, Heat Mirror, Aluminum Frames, Thermally Broken
0.37
0.37

Window/Wall Ratio: 28%

Wall/Roof

MaterialsEffective R-ValueTrombe Walls:Low-iron Patterned Trombe Wall, CMU (4)2.3Vistor Center Walls:Wood Siding, Rigid Insulation Board, Gypsum16.5Comfort Station Walls:Wood Siding, Rigid Insulation Board, CMU (4)6.6

Roof: Wood Shingles; Sheathing; Insulated Roof Panels 30.9

HVAC

<u>Heating</u> <u>Cooling</u>

Trombe Walls Operable Windows Electric Radiant Ceiling Panels 3 Cooling Towers

Lighting Power Densities(W/SF)

Main Area: (5) Offices: 1.0 Bookstore: 0.9

Energy/Power:

PV System: 7.2 kW grid-tie system

Net Annual Energy Usage (thousand Btu/SF*year): 27.0

Note(s): 1) Includes office, bookstore, and service areas 2) restroom complex 3) Solar heat gain coefficient 4) Concrete masonry unit 5) The main vistors

center area is handled almost entirely with daylighting. Auxiliary fluorescent lighting is used only occasionally to supplement.

Source(s): NREL, Evaluation of the Low-Energy Design and Energy Performance of the Zion National Park Visitors Center, Feb. 2005, p. 23-37;

NREL, Lessons Learned from Case Studies of Six High-Performance Buildings, June 2006, p. 5 Table A-2 p. 130.